CASE OF THE QUARTER


Joint peri-prosthetic case, the uncleansible full arch

Presented by: Dr Sunie Kundi & Dr Monal Patel



Patient Background

Mrs G was referred to our clinic presenting with an uncleansable FP1 implant-supported prosthesis. Clinical assessment revealed significant hygiene challenges and compromised aesthetic integration.







Clinical Findings

- Poorly contoured FP1 prosthesis, difficult to maintain hygiene.
- One failing implant requiring removal.
- Stripped screwhead embedded within the bridge complicating removal.
- Peri-implantitis and peri-implant mucositis affecting all implants.

Treatment Overview:

Failing implant carefully removed.

Stripped screwhead expertly retrieved, allowing for preservation of the prosthetic framework during assessment.

In house specialist periodontal management

A new FP3 prosthesis was designed and fitted

- Enhanced emergence profile
- Improved gingival aesthetics
- Increased cleansability and patient comfort
- Bespoke aesthetic tailored for patients' expectations

Call 02392 475 667 Email info@esp-dental.co.uk

www.emsworth-specialist-practice.co.uk
Emsworth Specialist Practice, 64 West Street, Havant, Hampshire PO9 1LN

Outcome

The transformation to an FP2-style bridge resulted in:

- Significantly improved patient hygiene capability.
- Restored aesthetic harmony.
- Long-term functional success.












Refer with Confidence

At Emsworth Specialist Practice, we prioritise both biological stability and aesthetic excellence in full-arch implant rehabilitation.

Call 02392 475 667 Email info@esp-dental.co.uk

www.emsworth-specialist-practice.co.uk
Emsworth Specialist Practice, 64 West Street, Havant, Hampshire PO9 1LN